

ประกาศชาวเรือ

หมายเลข 190/2552 (ล่วงหน้า)

ฝั่งตะวันตกของประเทศไทย

สตูล, ทางเข้าคลองท่าจีน, เกาะยาว ถึง แหลมปยู และ บ้านตำมะลัง ถึง บ้านตันหยงกาโอบย  
สายส่งกระแสไฟฟ้าใต้น้ำ

รายละเอียด — 1. สายส่งกระแสไฟฟ้าใต้น้ำ ได้วางแล้วลากเชื่อมต่อดำบลที่ (INDIAN1975 DATUM)

ดังต่อไปนี้ :

1.1 เกาะยาว ถึง แหลมปยู

- 1.1.1 แลต.  $6^{\circ} 28' 07''$ .5 น., ลอง.  $100^{\circ} 04' 29''$ .2 อ.
- 1.1.2 แลต.  $6^{\circ} 28' 11''$ .7 น., ลอง.  $100^{\circ} 04' 32''$ .0 อ.
- 1.1.3 แลต.  $6^{\circ} 28' 11''$ .8 น., ลอง.  $100^{\circ} 04' 32''$ .1 อ.
- 1.1.4 แลต.  $6^{\circ} 28' 12''$ .3 น., ลอง.  $100^{\circ} 04' 32''$ .6 อ.
- 1.1.5 แลต.  $6^{\circ} 28' 12''$ .8 น., ลอง.  $100^{\circ} 04' 33''$ .0 อ.
- 1.1.6 แลต.  $6^{\circ} 28' 13''$ .1 น., ลอง.  $100^{\circ} 04' 33''$ .3 อ.
- 1.1.7 แลต.  $6^{\circ} 28' 13''$ .6 น., ลอง.  $100^{\circ} 04' 33''$ .7 อ.
- 1.1.8 แลต.  $6^{\circ} 28' 13''$ .8 น., ลอง.  $100^{\circ} 04' 33''$ .9 อ.
- 1.1.9 แลต.  $6^{\circ} 28' 14''$ .3 น., ลอง.  $100^{\circ} 04' 33''$ .9 อ.
- 1.1.10 แลต.  $6^{\circ} 28' 14''$ .6 น., ลอง.  $100^{\circ} 04' 34''$ .3 อ.
- 1.1.11 แลต.  $6^{\circ} 28' 15''$ .0 น., ลอง.  $100^{\circ} 04' 34''$ .6 อ.
- 1.1.12 แลต.  $6^{\circ} 28' 15''$ .4 น., ลอง.  $100^{\circ} 04' 34''$ .8 อ.
- 1.1.13 แลต.  $6^{\circ} 28' 15''$ .6 น., ลอง.  $100^{\circ} 04' 34''$ .9 อ.
- 1.1.14 แลต.  $6^{\circ} 28' 15''$ .9 น., ลอง.  $100^{\circ} 04' 35''$ .2 อ.
- 1.1.15 แลต.  $6^{\circ} 28' 16''$ .4 น., ลอง.  $100^{\circ} 04' 35''$ .5 อ.
- 1.1.16 แลต.  $6^{\circ} 28' 16''$ .9 น., ลอง.  $100^{\circ} 04' 35''$ .9 อ.
- 1.1.17 แลต.  $6^{\circ} 28' 17''$ .5 น., ลอง.  $100^{\circ} 04' 36''$ .2 อ.
- 1.1.18 แลต.  $6^{\circ} 28' 18''$ .0 น., ลอง.  $100^{\circ} 04' 36''$ .6 อ.
- 1.1.19 แลต.  $6^{\circ} 28' 18''$ .4 น., ลอง.  $100^{\circ} 04' 37''$ .1 อ.
- 1.1.20 แลต.  $6^{\circ} 28' 19''$ .0 น., ลอง.  $100^{\circ} 04' 37''$ .4 อ.
- 1.1.21 แลต.  $6^{\circ} 28' 19''$ .5 น., ลอง.  $100^{\circ} 04' 37''$ .8 อ.
- 1.1.22 แลต.  $6^{\circ} 28' 20''$ .0 น., ลอง.  $100^{\circ} 04' 38''$ .1 อ.
- 1.1.23 แลต.  $6^{\circ} 28' 20''$ .3 น., ลอง.  $100^{\circ} 04' 38''$ .3 อ.
- 1.1.24 แลต.  $6^{\circ} 28' 20''$ .9 น., ลอง.  $100^{\circ} 04' 38''$ .4 อ.
- 1.1.25 แลต.  $6^{\circ} 28' 21''$ .4 น., ลอง.  $100^{\circ} 04' 38''$ .8 อ.
- 1.1.26 แลต.  $6^{\circ} 28' 22''$ .0 น., ลอง.  $100^{\circ} 04' 39''$ .0 อ.
- 1.1.27 แลต.  $6^{\circ} 28' 22''$ .5 น., ลอง.  $100^{\circ} 04' 39''$ .3 อ.

- 1.1.28 แลต. 6° 28' 23" .1 น., ลอง.100° 04' 39" .7 อ.  
1.1.29 แลต. 6° 28' 23" .6 น., ลอง.100° 04' 40" .0 อ.  
1.1.30 แลต. 6° 28' 23" .8 น., ลอง.100° 04' 40" .2 อ.  
1.1.31 แลต. 6° 28' 24" .3 น., ลอง.100° 04' 40" .5 อ.  
1.1.32 แลต. 6° 28' 24" .8 น., ลอง.100° 04' 40" .8 อ.  
1.1.33 แลต. 6° 28' 25" .3 น., ลอง.100° 04' 41" .2 อ.  
1.1.34 แลต. 6° 28' 25" .8 น., ลอง.100° 04' 41" .6 อ.  
1.1.35 แลต. 6° 28' 26" .2 น., ลอง.100° 04' 42" .1 อ.  
1.1.36 แลต. 6° 28' 26" .7 น., ลอง.100° 04' 42" .5 อ.  
1.1.37 แลต. 6° 28' 27" .1 น., ลอง.100° 04' 42" .9 อ.  
1.1.38 แลต. 6° 28' 27" .6 น., ลอง.100° 04' 43" .3 อ.  
1.1.39 แลต. 6° 28' 28" .1 น., ลอง.100° 04' 43" .6 อ.  
1.1.40 แลต. 6° 28' 28" .6 น., ลอง.100° 04' 43" .7 อ.  
1.1.41 แลต. 6° 28' 29" .0 น., ลอง.100° 04' 44" .1 อ.  
1.1.42 แลต. 6° 28' 29" .4 น., ลอง.100° 04' 44" .5 อ.  
1.1.43 แลต. 6° 28' 29" .7 น., ลอง.100° 04' 44" .7 อ.  
1.1.44 แลต. 6° 28' 30" .1 น., ลอง.100° 04' 44" .5 อ.  
1.1.45 แลต. 6° 28' 30" .6 น., ลอง.100° 04' 44" .8 อ.  
1.1.46 แลต. 6° 28' 31" .1 น., ลอง.100° 04' 45" .0 อ.  
1.1.47 แลต. 6° 28' 31" .7 น., ลอง.100° 04' 45" .3 อ.  
1.1.48 แลต. 6° 28' 32" .1 น., ลอง.100° 04' 45" .7 อ.  
1.1.49 แลต. 6° 28' 32" .6 น., ลอง.100° 04' 46" .1 อ.  
1.1.50 แลต. 6° 28' 33" .1 น., ลอง.100° 04' 46" .4 อ.  
1.1.51 แลต. 6° 28' 33" .7 น., ลอง.100° 04' 46" .8 อ.  
1.1.52 แลต. 6° 28' 34" .2 น., ลอง.100° 04' 47" .1 อ.  
1.1.53 แลต. 6° 28' 34" .8 น., ลอง.100° 04' 47" .5 อ.  
1.1.54 แลต. 6° 28' 35" .2 น., ลอง.100° 04' 48" .0 อ.  
1.1.55 แลต. 6° 28' 35" .6 น., ลอง.100° 04' 48" .3 อ.  
1.1.56 แลต. 6° 28' 35" .7 น., ลอง.100° 04' 48" .1 อ.  
1.1.57 แลต. 6° 28' 36" .2 น., ลอง.100° 04' 48" .5 อ.  
1.1.58 แลต. 6° 28' 36" .7 น., ลอง.100° 04' 48" .6 อ.  
1.1.59 แลต. 6° 28' 36" .6 น., ลอง.100° 04' 48" .9 อ.  
1.1.60 แลต. 6° 28' 37" .1 น., ลอง.100° 04' 49" .2 อ.  
1.1.61 แลต. 6° 28' 37" .6 น., ลอง.100° 04' 49" .5 อ.

- 1.1.62 แลต. 6° 28' 38" .2 น., ลอง.100° 04' 49" .9 อ.  
1.1.63 แลต. 6° 28' 38" .5 น., ลอง.100° 04' 50" .1 อ.  
1.1.64 แลต. 6° 28' 38" .7 น., ลอง.100° 04' 50" .2 อ.  
1.1.65 แลต. 6° 28' 39" .2 น., ลอง.100° 04' 50" .6 อ.  
1.1.66 แลต. 6° 28' 39" .6 น., ลอง.100° 04' 50" .8 อ.  
1.1.67 แลต. 6° 28' 40" .0 น., ลอง.100° 04' 51" .2 อ.  
1.1.68 แลต. 6° 28' 40" .3 น., ลอง.100° 04' 51" .7 อ.  
1.1.69 แลต. 6° 28' 40" .7 น., ลอง.100° 04' 52" .2 อ.  
1.1.70 แลต. 6° 28' 41" .0 น., ลอง.100° 04' 52" .8 อ.  
1.1.71 แลต. 6° 28' 41" .2 น., ลอง.100° 04' 53" .4 อ.  
1.1.72 แลต. 6° 28' 41" .5 น., ลอง.100° 04' 53" .9 อ.  
1.1.73 แลต. 6° 28' 41" .8 น., ลอง.100° 04' 54" .5 อ.  
1.1.74 แลต. 6° 28' 42" .2 น., ลอง.100° 04' 55" .0 อ.  
1.1.75 แลต. 6° 28' 42" .5 น., ลอง.100° 04' 55" .6 อ.  
1.1.76 แลต. 6° 28' 42" .9 น., ลอง.100° 04' 56" .1 อ.  
1.1.77 แลต. 6° 28' 43" .0 น., ลอง.100° 04' 56" .3 อ.  
1.1.78 แลต. 6° 28' 43" .0 น., ลอง.100° 04' 56" .8 อ.  
1.1.79 แลต. 6° 28' 43" .0 น., ลอง.100° 04' 56" .7 อ.  
1.1.80 แลต. 6° 28' 43" .3 น., ลอง.100° 04' 57" .4 อ.  
1.1.81 แลต. 6° 28' 43" .6 น., ลอง.100° 04' 57" .9 อ.  
1.1.82 แลต. 6° 28' 44" .1 น., ลอง.100° 04' 58" .1 อ.  
1.1.83 แลต. 6° 28' 44" .5 น., ลอง.100° 04' 58" .5 อ.  
1.1.84 แลต. 6° 28' 44" .7 น., ลอง.100° 04' 59" .0 อ.  
1.1.85 แลต. 6° 28' 45" .1 น., ลอง.100° 04' 59" .3 อ.  
1.1.86 แลต. 6° 28' 45" .6 น., ลอง.100° 04' 59" .4 อ.  
1.1.87 แลต. 6° 28' 46" .1 น., ลอง.100° 04' 59" .7 อ.  
1.1.88 แลต. 6° 28' 46" .5 น., ลอง.100° 05' 00" .0 อ.  
1.1.89 แลต. 6° 28' 47" .0 น., ลอง.100° 05' 00" .3 อ.  
1.1.90 แลต. 6° 28' 47" .3 น., ลอง.100° 05' 00" .6 อ.  
1.1.91 แลต. 6° 28' 47" .7 น., ลอง.100° 05' 01" .2 อ.  
1.1.92 แลต. 6° 28' 48" .1 น., ลอง.100° 05' 01" .7 อ.  
1.1.93 แลต. 6° 28' 48" .4 น., ลอง.100° 05' 01" .9 อ.  
1.1.94 แลต. 6° 28' 48" .9 น., ลอง.100° 05' 02" .3 อ.  
1.1.95 แลต. 6° 28' 49" .4 น., ลอง.100° 05' 02" .7 อ.  
1.1.96 แลต. 6° 28' 49" .9 น., ลอง.100° 05' 03" .0 อ.

- 1.1.97 แลต. 6° 28' 50" .5 น., ลอง.100° 05' 03" .4 อ.  
1.1.98 แลต. 6° 28' 51" .0 น., ลอง.100° 05' 03" .8 อ.  
1.1.99 แลต. 6° 28' 51" .5 น., ลอง.100° 05' 04" .2 อ.  
1.1.100 แลต. 6° 28' 52" .0 น., ลอง.100° 05' 04" .6 อ.  
1.1.101 แลต. 6° 28' 52" .5 น., ลอง.100° 05' 05" .0 อ.  
1.1.102 แลต. 6° 28' 53" .0 น., ลอง.100° 05' 05" .4 อ.  
1.1.103 แลต. 6° 28' 53" .6 น., ลอง.100° 05' 05" .7 อ.  
1.1.104 แลต. 6° 28' 54" .1 น., ลอง.100° 05' 06" .1 อ.  
1.1.105 แลต. 6° 28' 54" .3 น., ลอง.100° 05' 06" .3 อ.  
1.1.106 แลต. 6° 28' 54" .8 น., ลอง.100° 05' 06" .5 อ.  
1.1.107 แลต. 6° 28' 55" .4 น., ลอง.100° 05' 06" .7 อ.  
1.1.108 แลต. 6° 28' 55" .9 น., ลอง.100° 05' 07" .0 อ.  
1.1.109 แลต. 6° 28' 56" .5 น., ลอง.100° 05' 07" .4 อ.  
1.1.110 แลต. 6° 28' 57" .0 น., ลอง.100° 05' 07" .8 อ.  
1.1.111 แลต. 6° 28' 57" .4 น., ลอง.100° 05' 08" .2 อ.  
1.1.112 แลต. 6° 28' 57" .9 น., ลอง.100° 05' 08" .6 อ.  
1.1.113 แลต. 6° 28' 58" .3 น., ลอง.100° 05' 09" .0 อ.  
1.1.114 แลต. 6° 28' 58" .7 น., ลอง.100° 05' 09" .6 อ.  
1.1.115 แลต. 6° 28' 59" .1 น., ลอง.100° 05' 09" .9 อ.  
1.1.116 แลต. 6° 28' 59" .6 น., ลอง.100° 05' 10" .2 อ.  
1.1.117 แลต. 6° 29' 00" .2 น., ลอง.100° 05' 10" .5 อ.  
1.1.118 แลต. 6° 29' 00" .8 น., ลอง.100° 05' 10" .8 อ.  
1.1.119 แลต. 6° 29' 01" .1 น., ลอง.100° 05' 11" .2 อ.  
1.1.120 แลต. 6° 29' 01" .3 น., ลอง.100° 05' 11" .3 อ.  
1.1.121 แลต. 6° 29' 01" .8 น., ลอง.100° 05' 11" .7 อ.  
1.1.122 แลต. 6° 29' 02" .4 น., ลอง.100° 05' 12" .0 อ.  
1.1.123 แลต. 6° 29' 02" .9 น., ลอง.100° 05' 12" .4 อ.  
1.1.124 แลต. 6° 29' 03" .4 น., ลอง.100° 05' 12" .8 อ.  
1.1.125 แลต. 6° 29' 03" .8 น., ลอง.100° 05' 13" .1 อ.  
1.1.126 แลต. 6° 29' 03" .9 น., ลอง.100° 05' 13" .5 อ.  
1.1.127 แลต. 6° 29' 04" .3 น., ลอง.100° 05' 13" .7 อ.  
1.1.128 แลต. 6° 29' 04" .7 น., ลอง.100° 05' 13" .9 อ.  
1.1.129 แลต. 6° 29' 05" .1 น., ลอง.100° 05' 14" .4 อ.  
1.1.130 แลต. 6° 29' 05" .6 น., ลอง.100° 05' 14" .8 อ.  
1.1.131 แลต. 6° 29' 06" .1 น., ลอง.100° 05' 15" .1 อ.

- 1.1.132 แลต. 6° 29' 06" .5 น., ลอง.100° 05' 15" .6 อ.  
1.1.133 แลต. 6° 29' 07" .0 น., ลอง.100° 05' 15" .9 อ.  
1.1.134 แลต. 6° 29' 07" .5 น., ลอง.100° 05' 16" .3 อ.  
1.1.135 แลต. 6° 29' 07" .6 น., ลอง.100° 05' 16" .5 อ.  
1.1.136 แลต. 6° 29' 08" .2 น., ลอง.100° 05' 16" .8 อ.  
1.1.137 แลต. 6° 29' 08" .5 น., ลอง.100° 05' 17" .0 อ.  
1.1.138 แลต. 6° 29' 09" .0 น., ลอง.100° 05' 17" .3 อ.  
1.1.139 แลต. 6° 29' 09" .5 น., ลอง.100° 05' 17" .6 อ.  
1.1.140 แลต. 6° 29' 10" .1 น., ลอง.100° 05' 17" .9 อ.  
1.1.141 แลต. 6° 29' 10" .7 น., ลอง.100° 05' 18" .2 อ.  
1.1.142 แลต. 6° 29' 11" .2 น., ลอง.100° 05' 18" .7 อ.  
1.1.143 แลต. 6° 29' 11" .7 น., ลอง.100° 05' 19" .0 อ.  
1.1.144 แลต. 6° 29' 12" .2 น., ลอง.100° 05' 19" .4 อ.  
1.1.145 แลต. 6° 29' 12" .7 น., ลอง.100° 05' 19" .5 อ.  
1.1.146 แลต. 6° 29' 12" .9 น., ลอง.100° 05' 19" .6 อ.  
1.1.147 แลต. 6° 29' 13" .4 น., ลอง.100° 05' 20" .0 อ.  
1.1.148 แลต. 6° 29' 13" .8 น., ลอง.100° 05' 20" .4 อ.  
1.1.149 แลต. 6° 29' 14" .0 น., ลอง.100° 05' 20" .6 อ.  
1.1.150 แลต. 6° 29' 14" .4 น., ลอง.100° 05' 21" .1 อ.  
1.1.151 แลต. 6° 29' 14" .9 น., ลอง.100° 05' 21" .4 อ.  
1.1.152 แลต. 6° 29' 15" .4 น., ลอง.100° 05' 21" .8 อ.  
1.1.153 แลต. 6° 29' 15" .5 น., ลอง.100° 05' 21" .9 อ.  
1.1.154 แลต. 6° 29' 15" .9 น., ลอง.100° 05' 22" .2 อ.  
1.1.155 แลต. 6° 29' 16" .4 น., ลอง.100° 05' 22" .6 อ.  
1.1.156 แลต. 6° 29' 16" .8 น., ลอง.100° 05' 23" .0 อ.  
1.1.157 แลต. 6° 29' 17" .3 น., ลอง.100° 05' 23" .4 อ.  
1.1.158 แลต. 6° 29' 17" .7 น., ลอง.100° 05' 23" .8 อ.  
1.1.159 แลต. 6° 29' 18" .1 น., ลอง.100° 05' 24" .2 อ.  
1.1.160 แลต. 6° 29' 18" .2 น., ลอง.100° 05' 24" .3 อ.  
1.1.161 แลต. 6° 29' 18" .7 น., ลอง.100° 05' 24" .6 อ.  
1.1.162 แลต. 6° 29' 19" .2 น., ลอง.100° 05' 24" .9 อ.  
1.1.163 แลต. 6° 29' 19" .6 น., ลอง.100° 05' 25" .3 อ.  
1.1.164 แลต. 6° 29' 20" .1 น., ลอง.100° 05' 25" .7 อ.  
1.1.165 แลต. 6° 29' 21" .1 น., ลอง.100° 05' 26" .5 อ.  
1.1.166 แลต. 6° 29' 21" .5 น., ลอง.100° 05' 26" .8 อ.  
1.1.167 แลต. 6° 29' 21" .8 น., ลอง.100° 05' 27" .0 อ.

- 1.1.168 แลต. 6° 29' 22" .1 น., ลอง.100° 05' 27" .4 อ.
- 1.1.169 แลต. 6° 29' 22" .2 น., ลอง.100° 05' 27" .5 อ.
- 1.1.170 แลต. 6° 29' 22" .4 น., ลอง.100° 05' 27" .1 อ.
- 1.1.171 แลต. 6° 29' 22" .7 น., ลอง.100° 05' 27" .7 อ.
- 1.1.172 แลต. 6° 29' 23" .3 น., ลอง.100° 05' 28" .0 อ.
- 1.1.173 แลต. 6° 29' 23" .8 น., ลอง.100° 05' 28" .4 อ.
- 1.1.174 แลต. 6° 29' 24" .3 น., ลอง.100° 05' 28" .7 อ.
- 1.1.175 แลต. 6° 29' 24" .7 น., ลอง.100° 05' 29" .0 อ.
- 1.1.176 แลต. 6° 29' 24" .6 น., ลอง.100° 05' 29" .2 อ.
- 1.1.177 แลต. 6° 29' 24" .8 น., ลอง.100° 05' 29" .4 อ.
- 1.1.178 แลต. 6° 29' 25" .1 น., ลอง.100° 05' 29" .9 อ.
- 1.1.179 แลต. 6° 29' 25" .5 น., ลอง.100° 05' 30" .2 อ.
- 1.1.180 แลต. 6° 29' 25" .9 น., ลอง.100° 05' 30" .4 อ.
- 1.1.181 แลต. 6° 29' 26" .2 น., ลอง.100° 05' 30" .5 อ.
- 1.1.182 แลต. 6° 29' 26" .2 น., ลอง.100° 05' 30" .8 อ.
- 1.1.183 แลต. 6° 29' 26" .7 น., ลอง.100° 05' 31" .1 อ.
- 1.1.184 แลต. 6° 29' 27" .3 น., ลอง.100° 05' 31" .4 อ.
- 1.1.185 แลต. 6° 29' 27" .8 น., ลอง.100° 05' 31" .7 อ.
- 1.1.186 แลต. 6° 29' 28" .4 น., ลอง.100° 05' 32" .0 อ.
- 1.1.187 แลต. 6° 29' 28" .7 น., ลอง.100° 05' 31" .8 อ.
- 1.1.188 แลต. 6° 29' 36" .0 น., ลอง.100° 05' 33" .2 อ.

## 1.2 บ้านตำมะลัง ถึง บ้านต้นหยงกาโบย

- 1.2.1 แลต. 6° 31' 52" .2 น., ลอง.100° 04' 23" .2 อ.
- 1.2.2 แลต. 6° 31' 46" .7 น., ลอง.100° 04' 31" .2 อ.
- 1.2.3 แลต. 6° 31' 46" .6 น., ลอง.100° 04' 31" .3 อ.
- 1.2.4 แลต. 6° 31' 46" .1 น., ลอง.100° 04' 31" .9 อ.
- 1.2.5 แลต. 6° 31' 46" .5 น., ลอง.100° 04' 31" .3 อ.
- 1.2.6 แลต. 6° 31' 46" .1 น., ลอง.100° 04' 31" .8 อ.
- 1.2.7 แลต. 6° 31' 46" .1 น., ลอง.100° 04' 31" .9 อ.
- 1.2.8 แลต. 6° 31' 45" .6 น., ลอง.100° 04' 32" .2 อ.
- 1.2.9 แลต. 6° 31' 45" .5 น., ลอง.100° 04' 32" .4 อ.
- 1.2.10 แลต. 6° 31' 45" .0 น., ลอง.100° 04' 32" .4 อ.
- 1.2.11 แลต. 6° 31' 44" .6 น., ลอง.100° 04' 32" .8 อ.
- 1.2.12 แลต. 6° 31' 44" .1 น., ลอง.100° 04' 33" .1 อ.
- 1.2.13 แลต. 6° 31' 43" .7 น., ลอง.100° 04' 33" .5 อ.
- 1.2.14 แลต. 6° 31' 43" .2 น., ลอง.100° 04' 33" .8 อ.

- 1.2.15 แลต. 6° 31' 43" .1 น., ลอง.100° 04' 33" .9 อ.  
1.2.16 แลต. 6° 31' 43" .0 น., ลอง.100° 04' 33" .8 อ.  
1.2.17 แลต. 6° 31' 42" .6 น., ลอง.100° 04' 34" .2 อ.  
1.2.18 แลต. 6° 31' 42" .3 น., ลอง.100° 04' 34" .4 อ.  
1.2.19 แลต. 6° 31' 42" .2 น., ลอง.100° 04' 34" .5 อ.  
1.2.20 แลต. 6° 31' 42" .2 น., ลอง.100° 04' 34" .7 อ.  
1.2.21 แลต. 6° 31' 41" .9 น., ลอง.100° 04' 34" .8 อ.  
1.2.22 แลต. 6° 31' 41" .5 น., ลอง.100° 04' 35" .2 อ.  
1.2.23 แลต. 6° 31' 41" .1 น., ลอง.100° 04' 35" .7 อ.  
1.2.24 แลต. 6° 31' 40" .8 น., ลอง.100° 04' 36" .2 อ.  
1.2.25 แลต. 6° 31' 40" .6 น., ลอง.100° 04' 36" .7 อ.  
1.2.26 แลต. 6° 31' 40" .5 น., ลอง.100° 04' 37" .0 อ.  
1.2.27 แลต. 6° 31' 40" .5 น., ลอง.100° 04' 37" .2 อ.  
1.2.28 แลต. 6° 31' 40" .3 น., ลอง.100° 04' 37" .8 อ.  
1.2.29 แลต. 6° 31' 40" .0 น., ลอง.100° 04' 38" .3 อ.  
1.2.30 แลต. 6° 31' 39" .8 น., ลอง.100° 04' 38" .8 อ.  
1.2.31 แลต. 6° 31' 39" .6 น., ลอง.100° 04' 39" .2 อ.  
1.2.32 แลต. 6° 31' 39" .3 น., ลอง.100° 04' 39" .6 อ.  
1.2.33 แลต. 6° 31' 38" .9 น., ลอง.100° 04' 40" .1 อ.  
1.2.34 แลต. 6° 31' 38" .5 น., ลอง.100° 04' 40" .6 อ.  
1.2.35 แลต. 6° 31' 38" .2 น., ลอง.100° 04' 41" .1 อ.  
1.2.36 แลต. 6° 31' 37" .7 น., ลอง.100° 04' 41" .6 อ.  
1.2.37 แลต. 6° 31' 37" .5 น., ลอง.100° 04' 41" .8 อ.  
1.2.38 แลต. 6° 31' 37" .4 น., ลอง.100° 04' 42" .2 อ.  
1.2.39 แลต. 6° 31' 36" .9 น., ลอง.100° 04' 42" .7 อ.  
1.2.40 แลต. 6° 31' 36" .8 น., ลอง.100° 04' 42" .9 อ.  
1.2.41 แลต. 6° 31' 36" .3 น., ลอง.100° 04' 43" .3 อ.  
1.2.42 แลต. 6° 31' 35" .9 น., ลอง.100° 04' 43" .6 อ.  
1.2.43 แลต. 6° 31' 35" .4 น., ลอง.100° 04' 44" .1 อ.  
1.2.44 แลต. 6° 31' 35" .0 น., ลอง.100° 04' 44" .6 อ.  
1.2.45 แลต. 6° 31' 34" .6 น., ลอง.100° 04' 45" .0 อ.  
1.2.46 แลต. 6° 31' 34" .1 น., ลอง.100° 04' 45" .5 อ.  
1.2.47 แลต. 6° 31' 33" .7 น., ลอง.100° 04' 46" .0 อ.  
1.2.48 แลต. 6° 31' 33" .3 น., ลอง.100° 04' 46" .4 อ.  
1.2.49 แลต. 6° 31' 32" .8 น., ลอง.100° 04' 46" .9 อ.  
1.2.50 แลต. 6° 31' 32" .4 น., ลอง.100° 04' 47" .3 อ.

- 1.2.51 แลต. ๖° 31' 32" .0 น., ลอง.100° 04' 47" .8 อ.  
1.2.52 แลต. ๖° 31' 31" .5 น., ลอง.100° 04' 48" .3 อ.  
1.2.53 แลต. ๖° 31' 31" .1 น., ลอง.100° 04' 48" .8 อ.  
1.2.54 แลต. ๖° 31' 30" .9 น., ลอง.100° 04' 48" .8 อ.  
1.2.55 แลต. ๖° 31' 30" .6 น., ลอง.100° 04' 49" .4 อ.  
1.2.56 แลต. ๖° 31' 30" .2 น., ลอง.100° 04' 49" .9 อ.  
1.2.57 แลต. ๖° 31' 29" .8 น., ลอง.100° 04' 50" .3 อ.  
1.2.58 แลต. ๖° 31' 29" .4 น., ลอง.100° 04' 50" .7 อ.  
1.2.59 แลต. ๖° 31' 28" .9 น., ลอง.100° 04' 51" .1 อ.  
1.2.60 แลต. ๖° 31' 28" .6 น., ลอง.100° 04' 51" .6 อ.  
1.2.61 แลต. ๖° 31' 28" .2 น., ลอง.100° 04' 52" .1 อ.  
1.2.62 แลต. ๖° 31' 27" .7 น., ลอง.100° 04' 52" .5 อ.  
1.2.63 แลต. ๖° 31' 27" .3 น., ลอง.100° 04' 53" .0 อ.  
1.2.64 แลต. ๖° 31' 26" .9 น., ลอง.100° 04' 53" .4 อ.  
1.2.65 แลต. ๖° 31' 26" .5 น., ลอง.100° 04' 53" .9 อ.  
1.2.66 แลต. ๖° 31' 26" .0 น., ลอง.100° 04' 54" .3 อ.  
1.2.67 แลต. ๖° 31' 25" .8 น., ลอง.100° 04' 54" .7 อ.  
1.2.68 แลต. ๖° 31' 25" .2 น., ลอง.100° 04' 55" .1 อ.  
1.2.69 แลต. ๖° 31' 25" .0 น., ลอง.100° 04' 55" .5 อ.  
1.2.70 แลต. ๖° 31' 24" .9 น., ลอง.100° 04' 55" .3 อ.  
1.2.71 แลต. ๖° 31' 24" .6 น., ลอง.100° 04' 55" .8 อ.  
1.2.72 แลต. ๖° 31' 24" .1 น., ลอง.100° 04' 56" .3 อ.  
1.2.73 แลต. ๖° 31' 23" .6 น., ลอง.100° 04' 56" .7 อ.  
1.2.74 แลต. ๖° 31' 23" .2 น., ลอง.100° 04' 57" .2 อ.  
1.2.75 แลต. ๖° 31' 22" .7 น., ลอง.100° 04' 57" .6 อ.  
1.2.76 แลต. ๖° 31' 22" .3 น., ลอง.100° 04' 58" .1 อ.  
1.2.77 แลต. ๖° 31' 21" .9 น., ลอง.100° 04' 58" .5 อ.  
1.2.78 แลต. ๖° 31' 21" .4 น., ลอง.100° 04' 58" .9 อ.  
1.2.79 แลต. ๖° 31' 21" .0 น., ลอง.100° 04' 59" .4 อ.  
1.2.80 แลต. ๖° 31' 20" .6 น., ลอง.100° 04' 59" .8 อ.  
1.2.81 แลต. ๖° 31' 20" .1 น., ลอง.100° 05' 00" .3 อ.  
1.2.82 แลต. ๖° 31' 19" .7 น., ลอง.100° 05' 00" .7 อ.  
1.2.83 แลต. ๖° 31' 19" .6 น., ลอง.100° 05' 01" .0 อ.  
1.2.84 แลต. ๖° 31' 19" .2 น., ลอง.100° 05' 01" .4 อ.



- 1.2.85 แลต. 6° 31' 18" .8 น., ลอง. 100° 05' 01" .9 อ.  
1.2.86 แลต. 6° 31' 18" .6 น., ลอง. 100° 05' 02" .1 อ.  
1.2.87 แลต. 6° 31' 18" .5 น., ลอง. 100° 05' 02" .1 อ.  
1.2.88 แลต. 6° 31' 18" .4 น., ลอง. 100° 05' 02" .3 อ.  
1.2.89 แลต. 6° 31' 18" .0 น., ลอง. 100° 05' 02" .8 อ.  
1.2.90 แลต. 6° 31' 17" .7 น., ลอง. 100° 05' 03" .3 อ.  
1.2.91 แลต. 6° 31' 17" .3 น., ลอง. 100° 05' 03" .8 อ.  
1.2.92 แลต. 6° 31' 17" .0 น., ลอง. 100° 05' 04" .3 อ.  
1.2.93 แลต. 6° 31' 16" .5 น., ลอง. 100° 05' 04" .7 อ.  
1.2.94 แลต. 6° 31' 16" .2 น., ลอง. 100° 05' 05" .3 อ.  
1.2.95 แลต. 6° 31' 15" .8 น., ลอง. 100° 05' 05" .7 อ.  
1.2.96 แลต. 6° 31' 15" .3 น., ลอง. 100° 05' 06" .2 อ.  
1.2.97 แลต. 6° 31' 14" .9 น., ลอง. 100° 05' 06" .7 อ.  
1.2.98 แลต. 6° 31' 14" .5 น., ลอง. 100° 05' 07" .2 อ.  
1.2.99 แลต. 6° 31' 14" .0 น., ลอง. 100° 05' 07" .7 อ.  
1.2.100 แลต. 6° 31' 13" .6 น., ลอง. 100° 05' 08" .1 อ.  
1.2.101 แลต. 6° 31' 13" .1 น., ลอง. 100° 05' 08" .6 อ.  
1.2.102 แลต. 6° 31' 12" .7 น., ลอง. 100° 05' 08" .9 อ.  
1.2.103 แลต. 6° 31' 12" .8 น., ลอง. 100° 05' 09" .0 อ.  
1.2.104 แลต. 6° 31' 12" .8 น., ลอง. 100° 05' 09" .1 อ.  
1.2.105 แลต. 6° 31' 12" .6 น., ลอง. 100° 05' 09" .4 อ.  
1.2.106 แลต. 6° 31' 12" .2 น., ลอง. 100° 05' 09" .9 อ.  
1.2.107 แลต. 6° 31' 11" .9 น., ลอง. 100° 05' 10" .4 อ.  
1.2.108 แลต. 6° 31' 11" .4 น., ลอง. 100° 05' 10" .9 อ.  
1.2.109 แลต. 6° 31' 11" .0 น., ลอง. 100° 05' 11" .2 อ.  
1.2.110 แลต. 6° 31' 10" .6 น., ลอง. 100° 05' 11" .7 อ.  
1.2.111 แลต. 6° 31' 10" .1 น., ลอง. 100° 05' 12" .2 อ.  
1.2.112 แลต. 6° 31' 09" .7 น., ลอง. 100° 05' 12" .7 อ.  
1.2.113 แลต. 6° 31' 09" .2 น., ลอง. 100° 05' 13" .1 อ.  
1.2.114 แลต. 6° 31' 08" .7 น., ลอง. 100° 05' 13" .6 อ.  
1.2.115 แลต. 6° 31' 08" .3 น., ลอง. 100° 05' 14" .0 อ.  
1.2.116 แลต. 6° 31' 07" .8 น., ลอง. 100° 05' 14" .5 อ.  
1.2.117 แลต. 6° 31' 07" .3 น., ลอง. 100° 05' 14" .9 อ.  
1.2.118 แลต. 6° 31' 06" .9 น., ลอง. 100° 05' 15" .4 อ.  
1.2.119 แลต. 6° 31' 06" .4 น., ลอง. 100° 05' 15" .8 อ.

- 1.2.120 แลต. 6° 31' 06" .1 น., ลอง.100° 05' 16" .3 อ.  
1.2.121 แลต. 6° 31' 06" .2 น., ลอง.100° 05' 16" .3 อ.  
1.2.122 แลต. 6° 31' 06" .0 น., ลอง.100° 05' 16" .2 อ.  
1.2.123 แลต. 6° 31' 06" .0 น., ลอง.100° 05' 16" .3 อ.  
1.2.124 แลต. 6° 31' 05" .5 น., ลอง.100° 05' 16" .7 อ.  
1.2.125 แลต. 6° 31' 05" .0 น., ลอง.100° 05' 17" .2 อ.  
1.2.126 แลต. 6° 31' 04" .5 น., ลอง.100° 05' 17" .6 อ.  
1.2.127 แลต. 6° 31' 04" .0 น., ลอง.100° 05' 18" .1 อ.  
1.2.128 แลต. 6° 31' 03" .6 น., ลอง.100° 05' 18" .5 อ.  
1.2.129 แลต. 6° 31' 03" .1 น., ลอง.100° 05' 19" .0 อ.  
1.2.130 แลต. 6° 31' 02" .7 น., ลอง.100° 05' 19" .4 อ.  
1.2.131 แลต. 6° 31' 02" .3 น., ลอง.100° 05' 19" .9 อ.  
1.2.132 แลต. 6° 31' 01" .8 น., ลอง.100° 05' 20" .3 อ.  
1.2.133 แลต. 6° 31' 01" .3 น., ลอง.100° 05' 20" .7 อ.  
1.2.134 แลต. 6° 31' 00" .8 น., ลอง.100° 05' 21" .2 อ.  
1.2.135 แลต. 6° 31' 00" .6 น., ลอง.100° 05' 21" .2 อ.  
1.2.136 แลต. 6° 31' 00" .5 น., ลอง.100° 05' 21" .7 อ.  
1.2.137 แลต. 6° 31' 00" .2 น., ลอง.100° 05' 22" .2 อ.  
1.2.138 แลต. 6° 30' 59" .8 น., ลอง.100° 05' 22" .7 อ.  
1.2.139 แลต. 6° 30' 59" .6 น., ลอง.100° 05' 22" .8 อ.  
1.2.140 แลต. 6° 30' 59" .4 น., ลอง.100° 05' 23" .1 อ.  
1.2.141 แลต. 6° 30' 59" .1 น., ลอง.100° 05' 23" .6 อ.  
1.2.142 แลต. 6° 30' 58" .7 น., ลอง.100° 05' 24" .2 อ.  
1.2.143 แลต. 6° 30' 58" .3 น., ลอง.100° 05' 24" .6 อ.  
1.2.144 แลต. 6° 30' 57" .9 น., ลอง.100° 05' 25" .1 อ.  
1.2.145 แลต. 6° 30' 57" .4 น., ลอง.100° 05' 25" .6 อ.  
1.2.146 แลต. 6° 30' 57" .0 น., ลอง.100° 05' 26" .1 อ.  
1.2.147 แลต. 6° 30' 56" .2 น., ลอง.100° 05' 27" .1 อ.  
1.2.148 แลต. 6° 30' 55" .7 น., ลอง.100° 05' 27" .5 อ.  
1.2.149 แลต. 6° 30' 55" .3 น., ลอง.100° 05' 28" .0 อ.  
1.2.150 แลต. 6° 30' 54" .8 น., ลอง.100° 05' 28" .5 อ.  
1.2.151 แลต. 6° 30' 54" .9 น., ลอง.100° 05' 28" .6 อ.  
1.2.152 แลต. 6° 30' 54" .4 น., ลอง.100° 05' 29" .0 อ.

- 1.2.153 แลต. 6° 30' 53" .9 น., ลอง.100° 05' 29" .5 อ.  
1.2.154 แลต. 6° 30' 53" .6 น., ลอง.100° 05' 29" .9 อ.  
1.2.155 แลต. 6° 30' 53" .4 น., ลอง.100° 05' 30" .0 อ.  
1.2.156 แลต. 6° 30' 53" .4 น., ลอง.100° 05' 29" .9 อ.  
1.2.157 แลต. 6° 30' 53" .3 น., ลอง.100° 05' 30" .4 อ.  
1.2.158 แลต. 6° 30' 52" .9 น., ลอง.100° 05' 30" .8 อ.  
1.2.159 แลต. 6° 30' 52" .5 น., ลอง.100° 05' 31" .3 อ.  
1.2.160 แลต. 6° 30' 52" .1 น., ลอง.100° 05' 31" .8 อ.  
1.2.161 แลต. 6° 30' 51" .6 น., ลอง.100° 05' 32" .1 อ.  
1.2.162 แลต. 6° 30' 51" .1 น., ลอง.100° 05' 32" .5 อ.  
1.2.163 แลต. 6° 30' 50" .7 น., ลอง.100° 05' 32" .9 อ.  
1.2.164 แลต. 6° 30' 50" .3 น., ลอง.100° 05' 33" .4 อ.  
1.2.165 แลต. 6° 30' 49" .9 น., ลอง.100° 05' 33" .9 อ.  
1.2.166 แลต. 6° 30' 49" .4 น., ลอง.100° 05' 34" .3 อ.  
1.2.167 แลต. 6° 30' 48" .9 น., ลอง.100° 05' 34" .8 อ.  
1.2.168 แลต. 6° 30' 48" .5 น., ลอง.100° 05' 35" .2 อ.  
1.2.169 แลต. 6° 30' 48" .0 น., ลอง.100° 05' 35" .7 อ.  
1.2.170 แลต. 6° 30' 47" .6 น., ลอง.100° 05' 36" .1 อ.  
1.2.171 แลต. 6° 30' 47" .4 น., ลอง.100° 05' 36" .4 อ.  
1.2.172 แลต. 6° 30' 47" .1 น., ลอง.100° 05' 36" .4 อ.  
1.2.173 แลต. 6° 30' 46" .6 น., ลอง.100° 05' 36" .8 อ.  
1.2.174 แลต. 6° 30' 46" .3 น., ลอง.100° 05' 37" .2 อ.  
1.2.175 แลต. 6° 30' 46" .1 น., ลอง.100° 05' 37" .7 อ.  
1.2.176 แลต. 6° 30' 46" .0 น., ลอง.100° 05' 37" .7 อ.  
1.2.177 แลต. 6° 30' 45" .5 น., ลอง.100° 05' 38" .1 อ.  
1.2.178 แลต. 6° 30' 45" .2 น., ลอง.100° 05' 38" .6 อ.  
1.2.179 แลต. 6° 30' 44" .8 น., ลอง.100° 05' 39" .1 อ.  
1.2.180 แลต. 6° 30' 44" .5 น., ลอง.100° 05' 39" .6 อ.  
1.2.181 แลต. 6° 30' 44" .1 น., ลอง.100° 05' 40" .0 อ.  
1.2.182 แลต. 6° 30' 43" .7 น., ลอง.100° 05' 40" .5 อ.  
1.2.183 แลต. 6° 30' 43" .3 น., ลอง.100° 05' 41" .0 อ.  
1.2.184 แลต. 6° 30' 42" .9 น., ลอง.100° 05' 41" .5 อ.

- 1.2.185 แลต.  $6^{\circ} 30' 43''$ .3 น., ลอง.  $100^{\circ} 05' 41''$ .0 อ.  
1.2.186 แลต.  $6^{\circ} 30' 42''$ .5 น., ลอง.  $100^{\circ} 05' 41''$ .9 อ.  
1.2.187 แลต.  $6^{\circ} 30' 42''$ .1 น., ลอง.  $100^{\circ} 05' 42''$ .4 อ.  
1.2.188 แลต.  $6^{\circ} 30' 41''$ .7 น., ลอง.  $100^{\circ} 05' 42''$ .9 อ.  
1.2.189 แลต.  $6^{\circ} 30' 41''$ .4 น., ลอง.  $100^{\circ} 05' 43''$ .4 อ.  
1.2.190 แลต.  $6^{\circ} 30' 41''$ .3 น., ลอง.  $100^{\circ} 05' 43''$ .9 อ.  
1.2.191 แลต.  $6^{\circ} 30' 36''$ .8 น., ลอง.  $100^{\circ} 05' 47''$ .8 อ.

2. เรือควรถูกเลิกกิจการทอดสมอ หรือใช้เรือลากอวน บริเวณของเส้นทางสายส่ง  
กระแสไฟฟ้าใต้น้ำ
3. สายส่งกระแสไฟฟ้าใต้น้ำ จะรวบรวมไว้ในบรรณาธิกรครั้งต่อไปของแผนที่ 362  
และ 045, แผนที่ 350 และ 309 ปรับปรุงโดยประกาศชาวเรือ
4. ประกาศชาวเรือครั้งก่อน หมายเลข 7/2552 (ล่องหน้า) ยกเลิก

แผนที่ซึ่งเกี่ยวข้อง — แผนที่เดินเรือไทย หมายเลข 350, 309, 362 และ 045  
รายงานจาก — การไฟฟ้าส่วนภูมิภาค, ลง 22 กรกฎาคม 2552

ประกาศโดยกรมอุทกศาสตร์  
กองทัพเรือ กรุงเทพฯ ฯ  
17 ธันวาคม 2552

Notice to Mariners

No. 190/2552 (Preliminary)

WEST COAST OF THAILAND

Satun, Entrance to Khlong Tha Chin, Ko Yao to Laem Puyu and  
Ban Tammalang to Ban Tanyong Kaboi -- Submarine power cables.

---

Details :

1. Submarine power cables have been laid joining the following positions (INDIAN  
1975 DATUM) :

1.1 Ko Yao to Laem Puyu

- 1.1.1 Lat.  $6^{\circ} 28' 07''$  .5 N., Long.  $100^{\circ} 04' 29''$  .2 E.
- 1.1.2 Lat.  $6^{\circ} 28' 11''$  .7 N., Long.  $100^{\circ} 04' 32''$  .0 E.
- 1.1.3 Lat.  $6^{\circ} 28' 11''$  .8 N., Long.  $100^{\circ} 04' 32''$  .1 E.
- 1.1.4 Lat.  $6^{\circ} 28' 12''$  .3 N., Long.  $100^{\circ} 04' 32''$  .6 E.
- 1.1.5 Lat.  $6^{\circ} 28' 12''$  .8 N., Long.  $100^{\circ} 04' 33''$  .0 E.
- 1.1.6 Lat.  $6^{\circ} 28' 13''$  .1 N., Long.  $100^{\circ} 04' 33''$  .3 E.
- 1.1.7 Lat.  $6^{\circ} 28' 13''$  .6 N., Long.  $100^{\circ} 04' 33''$  .7 E.
- 1.1.8 Lat.  $6^{\circ} 28' 13''$  .8 N., Long.  $100^{\circ} 04' 33''$  .9 E.
- 1.1.9 Lat.  $6^{\circ} 28' 14''$  .3 N., Long.  $100^{\circ} 04' 33''$  .9 E.
- 1.1.10 Lat.  $6^{\circ} 28' 14''$  .6 N., Long.  $100^{\circ} 04' 34''$  .3 E.
- 1.1.11 Lat.  $6^{\circ} 28' 15''$  .0 N., Long.  $100^{\circ} 04' 34''$  .6 E.
- 1.1.12 Lat.  $6^{\circ} 28' 15''$  .4 N., Long.  $100^{\circ} 04' 34''$  .8 E.
- 1.1.13 Lat.  $6^{\circ} 28' 15''$  .6 N., Long.  $100^{\circ} 04' 34''$  .9 E.
- 1.1.14 Lat.  $6^{\circ} 28' 15''$  .9 N., Long.  $100^{\circ} 04' 35''$  .2 E.
- 1.1.15 Lat.  $6^{\circ} 28' 16''$  .4 N., Long.  $100^{\circ} 04' 35''$  .5 E.
- 1.1.16 Lat.  $6^{\circ} 28' 16''$  .9 N., Long.  $100^{\circ} 04' 35''$  .9 E.
- 1.1.17 Lat.  $6^{\circ} 28' 17''$  .5 N., Long.  $100^{\circ} 04' 36''$  .2 E.
- 1.1.18 Lat.  $6^{\circ} 28' 18''$  .0 N., Long.  $100^{\circ} 04' 36''$  .6 E.
- 1.1.19 Lat.  $6^{\circ} 28' 18''$  .4 N., Long.  $100^{\circ} 04' 37''$  .1 E.
- 1.1.20 Lat.  $6^{\circ} 28' 19''$  .0 N., Long.  $100^{\circ} 04' 37''$  .4 E.
- 1.1.21 Lat.  $6^{\circ} 28' 19''$  .5 N., Long.  $100^{\circ} 04' 37''$  .8 E.
- 1.1.22 Lat.  $6^{\circ} 28' 20''$  .0 N., Long.  $100^{\circ} 04' 38''$  .1 E.
- 1.1.23 Lat.  $6^{\circ} 28' 20''$  .3 N., Long.  $100^{\circ} 04' 38''$  .3 E.
- 1.1.24 Lat.  $6^{\circ} 28' 20''$  .9 N., Long.  $100^{\circ} 04' 38''$  .4 E.
- 1.1.25 Lat.  $6^{\circ} 28' 21''$  .4 N., Long.  $100^{\circ} 04' 38''$  .8 E.
- 1.1.26 Lat.  $6^{\circ} 28' 22''$  .0 N., Long.  $100^{\circ} 04' 39''$  .0 E.
- 1.1.27 Lat.  $6^{\circ} 28' 22''$  .5 N., Long.  $100^{\circ} 04' 39''$  .3 E.
- 1.1.28 Lat.  $6^{\circ} 28' 23''$  .1 N., Long.  $100^{\circ} 04' 39''$  .7 E.

- 1.1.29 Lat.  $6^{\circ} 28' 23''$  .6 N., Long.  $100^{\circ} 04' 40''$  .0 E.  
1.1.30 Lat.  $6^{\circ} 28' 23''$  .8 N., Long.  $100^{\circ} 04' 40''$  .2 E.  
1.1.31 Lat.  $6^{\circ} 28' 24''$  .3 N., Long.  $100^{\circ} 04' 40''$  .5 E.  
1.1.32 Lat.  $6^{\circ} 28' 24''$  .8 N., Long.  $100^{\circ} 04' 40''$  .8 E.  
1.1.33 Lat.  $6^{\circ} 28' 25''$  .3 N., Long.  $100^{\circ} 04' 41''$  .2 E.  
1.1.34 Lat.  $6^{\circ} 28' 25''$  .8 N., Long.  $100^{\circ} 04' 41''$  .6 E.  
1.1.35 Lat.  $6^{\circ} 28' 26''$  .2 N., Long.  $100^{\circ} 04' 42''$  .1 E.  
1.1.36 Lat.  $6^{\circ} 28' 26''$  .7 N., Long.  $100^{\circ} 04' 42''$  .5 E.  
1.1.37 Lat.  $6^{\circ} 28' 27''$  .1 N., Long.  $100^{\circ} 04' 42''$  .9 E.  
1.1.38 Lat.  $6^{\circ} 28' 27''$  .6 N., Long.  $100^{\circ} 04' 43''$  .3 E.  
1.1.39 Lat.  $6^{\circ} 28' 28''$  .1 N., Long.  $100^{\circ} 04' 43''$  .6 E.  
1.1.40 Lat.  $6^{\circ} 28' 28''$  .6 N., Long.  $100^{\circ} 04' 43''$  .7 E.  
1.1.41 Lat.  $6^{\circ} 28' 29''$  .0 N., Long.  $100^{\circ} 04' 44''$  .1 E.  
1.1.42 Lat.  $6^{\circ} 28' 29''$  .4 N., Long.  $100^{\circ} 04' 44''$  .5 E.  
1.1.43 Lat.  $6^{\circ} 28' 29''$  .7 N., Long.  $100^{\circ} 04' 44''$  .7 E.  
1.1.44 Lat.  $6^{\circ} 28' 30''$  .1 N., Long.  $100^{\circ} 04' 44''$  .5 E.  
1.1.45 Lat.  $6^{\circ} 28' 30''$  .6 N., Long.  $100^{\circ} 04' 44''$  .8 E.  
1.1.46 Lat.  $6^{\circ} 28' 31''$  .1 N., Long.  $100^{\circ} 04' 45''$  .0 E.  
1.1.47 Lat.  $6^{\circ} 28' 31''$  .7 N., Long.  $100^{\circ} 04' 45''$  .3 E.  
1.1.48 Lat.  $6^{\circ} 28' 32''$  .1 N., Long.  $100^{\circ} 04' 45''$  .7 E.  
1.1.49 Lat.  $6^{\circ} 28' 32''$  .6 N., Long.  $100^{\circ} 04' 46''$  .1 E.  
1.1.50 Lat.  $6^{\circ} 28' 33''$  .1 N., Long.  $100^{\circ} 04' 46''$  .4 E.  
1.1.51 Lat.  $6^{\circ} 28' 33''$  .7 N., Long.  $100^{\circ} 04' 46''$  .8 E.  
1.1.52 Lat.  $6^{\circ} 28' 34''$  .2 N., Long.  $100^{\circ} 04' 47''$  .1 E.  
1.1.53 Lat.  $6^{\circ} 28' 34''$  .8 N., Long.  $100^{\circ} 04' 47''$  .5 E.  
1.1.54 Lat.  $6^{\circ} 28' 35''$  .2 N., Long.  $100^{\circ} 04' 48''$  .0 E.  
1.1.55 Lat.  $6^{\circ} 28' 35''$  .6 N., Long.  $100^{\circ} 04' 48''$  .3 E.  
1.1.56 Lat.  $6^{\circ} 28' 35''$  .7 N., Long.  $100^{\circ} 04' 48''$  .1 E.  
1.1.57 Lat.  $6^{\circ} 28' 36''$  .2 N., Long.  $100^{\circ} 04' 48''$  .5 E.  
1.1.58 Lat.  $6^{\circ} 28' 36''$  .7 N., Long.  $100^{\circ} 04' 48''$  .6 E.  
1.1.59 Lat.  $6^{\circ} 28' 36''$  .6 N., Long.  $100^{\circ} 04' 48''$  .9 E.  
1.1.60 Lat.  $6^{\circ} 28' 37''$  .1 N., Long.  $100^{\circ} 04' 49''$  .2 E.  
1.1.61 Lat.  $6^{\circ} 28' 37''$  .6 N., Long.  $100^{\circ} 04' 49''$  .5 E.  
1.1.62 Lat.  $6^{\circ} 28' 38''$  .2 N., Long.  $100^{\circ} 04' 49''$  .9 E.  
1.1.63 Lat.  $6^{\circ} 28' 38''$  .5 N., Long.  $100^{\circ} 04' 50''$  .1 E.

- 1.1.64 Lat.  $6^{\circ} 28' 38''$ .7 N., Long.  $100^{\circ} 04' 50''$ .2 E.  
1.1.65 Lat.  $6^{\circ} 28' 39''$ .2 N., Long.  $100^{\circ} 04' 50''$ .6 E.  
1.1.66 Lat.  $6^{\circ} 28' 39''$ .6 N., Long.  $100^{\circ} 04' 50''$ .8 E.  
1.1.67 Lat.  $6^{\circ} 28' 40''$ .0 N., Long.  $100^{\circ} 04' 51''$ .2 E.  
1.1.68 Lat.  $6^{\circ} 28' 40''$ .3 N., Long.  $100^{\circ} 04' 51''$ .7 E.  
1.1.69 Lat.  $6^{\circ} 28' 40''$ .7 N., Long.  $100^{\circ} 04' 52''$ .2 E.  
1.1.70 Lat.  $6^{\circ} 28' 41''$ .0 N., Long.  $100^{\circ} 04' 52''$ .8 E.  
1.1.71 Lat.  $6^{\circ} 28' 41''$ .2 N., Long.  $100^{\circ} 04' 53''$ .4 E.  
1.1.72 Lat.  $6^{\circ} 28' 41''$ .5 N., Long.  $100^{\circ} 04' 53''$ .9 E.  
1.1.73 Lat.  $6^{\circ} 28' 41''$ .8 N., Long.  $100^{\circ} 04' 54''$ .5 E.  
1.1.74 Lat.  $6^{\circ} 28' 42''$ .2 N., Long.  $100^{\circ} 04' 55''$ .0 E.  
1.1.75 Lat.  $6^{\circ} 28' 42''$ .5 N., Long.  $100^{\circ} 04' 55''$ .6 E.  
1.1.76 Lat.  $6^{\circ} 28' 42''$ .9 N., Long.  $100^{\circ} 04' 56''$ .1 E.  
1.1.77 Lat.  $6^{\circ} 28' 43''$ .0 N., Long.  $100^{\circ} 04' 56''$ .3 E.  
1.1.78 Lat.  $6^{\circ} 28' 43''$ .0 N., Long.  $100^{\circ} 04' 56''$ .8 E.  
1.1.79 Lat.  $6^{\circ} 28' 43''$ .0 N., Long.  $100^{\circ} 04' 56''$ .7 E.  
1.1.80 Lat.  $6^{\circ} 28' 43''$ .3 N., Long.  $100^{\circ} 04' 57''$ .4 E.  
1.1.81 Lat.  $6^{\circ} 28' 43''$ .6 N., Long.  $100^{\circ} 04' 57''$ .9 E.  
1.1.82 Lat.  $6^{\circ} 28' 44''$ .1 N., Long.  $100^{\circ} 04' 58''$ .1 E.  
1.1.83 Lat.  $6^{\circ} 28' 44''$ .5 N., Long.  $100^{\circ} 04' 58''$ .5 E.  
1.1.84 Lat.  $6^{\circ} 28' 44''$ .7 N., Long.  $100^{\circ} 04' 59''$ .0 E.  
1.1.85 Lat.  $6^{\circ} 28' 45''$ .1 N., Long.  $100^{\circ} 04' 59''$ .3 E.  
1.1.86 Lat.  $6^{\circ} 28' 45''$ .6 N., Long.  $100^{\circ} 04' 59''$ .4 E.  
1.1.87 Lat.  $6^{\circ} 28' 46''$ .1 N., Long.  $100^{\circ} 04' 59''$ .7 E.  
1.1.88 Lat.  $6^{\circ} 28' 46''$ .5 N., Long.  $100^{\circ} 05' 00''$ .0 E.  
1.1.89 Lat.  $6^{\circ} 28' 47''$ .0 N., Long.  $100^{\circ} 05' 00''$ .3 E.  
1.1.90 Lat.  $6^{\circ} 28' 47''$ .3 N., Long.  $100^{\circ} 05' 00''$ .6 E.  
1.1.91 Lat.  $6^{\circ} 28' 47''$ .7 N., Long.  $100^{\circ} 05' 01''$ .2 E.  
1.1.92 Lat.  $6^{\circ} 28' 48''$ .1 N., Long.  $100^{\circ} 05' 01''$ .7 E.  
1.1.93 Lat.  $6^{\circ} 28' 48''$ .4 N., Long.  $100^{\circ} 05' 01''$ .9 E.  
1.1.94 Lat.  $6^{\circ} 28' 48''$ .9 N., Long.  $100^{\circ} 05' 02''$ .3 E.  
1.1.95 Lat.  $6^{\circ} 28' 49''$ .4 N., Long.  $100^{\circ} 05' 02''$ .7 E.  
1.1.96 Lat.  $6^{\circ} 28' 49''$ .9 N., Long.  $100^{\circ} 05' 03''$ .0 E.  
1.1.97 Lat.  $6^{\circ} 28' 50''$ .5 N., Long.  $100^{\circ} 05' 03''$ .4 E.  
1.1.98 Lat.  $6^{\circ} 28' 51''$ .0 N., Long.  $100^{\circ} 05' 03''$ .8 E.

1.1.99 Lat.  $6^{\circ} 28' 51'' .5$  N., Long.  $100^{\circ} 05' 04'' .2$  E.  
1.1.100 Lat.  $6^{\circ} 28' 52'' .0$  N., Long.  $100^{\circ} 05' 04'' .6$  E.  
1.1.101 Lat.  $6^{\circ} 28' 52'' .5$  N., Long.  $100^{\circ} 05' 05'' .0$  E.  
1.1.102 Lat.  $6^{\circ} 28' 53'' .0$  N., Long.  $100^{\circ} 05' 05'' .4$  E.  
1.1.103 Lat.  $6^{\circ} 28' 53'' .6$  N., Long.  $100^{\circ} 05' 05'' .7$  E.  
1.1.104 Lat.  $6^{\circ} 28' 54'' .1$  N., Long.  $100^{\circ} 05' 06'' .1$  E.  
1.1.105 Lat.  $6^{\circ} 28' 54'' .3$  N., Long.  $100^{\circ} 05' 06'' .3$  E.  
1.1.106 Lat.  $6^{\circ} 28' 54'' .8$  N., Long.  $100^{\circ} 05' 06'' .5$  E.  
1.1.107 Lat.  $6^{\circ} 28' 55'' .4$  N., Long.  $100^{\circ} 05' 06'' .7$  E.  
1.1.108 Lat.  $6^{\circ} 28' 55'' .9$  N., Long.  $100^{\circ} 05' 07'' .0$  E.  
1.1.109 Lat.  $6^{\circ} 28' 56'' .5$  N., Long.  $100^{\circ} 05' 07'' .4$  E.  
1.1.110 Lat.  $6^{\circ} 28' 57'' .0$  N., Long.  $100^{\circ} 05' 07'' .8$  E.  
1.1.111 Lat.  $6^{\circ} 28' 57'' .4$  N., Long.  $100^{\circ} 05' 08'' .2$  E.  
1.1.112 Lat.  $6^{\circ} 28' 57'' .9$  N., Long.  $100^{\circ} 05' 08'' .6$  E.  
1.1.113 Lat.  $6^{\circ} 28' 58'' .3$  N., Long.  $100^{\circ} 05' 09'' .0$  E.  
1.1.114 Lat.  $6^{\circ} 28' 58'' .7$  N., Long.  $100^{\circ} 05' 09'' .6$  E.  
1.1.115 Lat.  $6^{\circ} 28' 59'' .1$  N., Long.  $100^{\circ} 05' 09'' .9$  E.  
1.1.116 Lat.  $6^{\circ} 28' 59'' .6$  N., Long.  $100^{\circ} 05' 10'' .2$  E.  
1.1.117 Lat.  $6^{\circ} 29' 00'' .2$  N., Long.  $100^{\circ} 05' 10'' .5$  E.  
1.1.118 Lat.  $6^{\circ} 29' 00'' .8$  N., Long.  $100^{\circ} 05' 10'' .8$  E.  
1.1.119 Lat.  $6^{\circ} 29' 01'' .1$  N., Long.  $100^{\circ} 05' 11'' .2$  E.  
1.1.120 Lat.  $6^{\circ} 29' 01'' .3$  N., Long.  $100^{\circ} 05' 11'' .3$  E.  
1.1.121 Lat.  $6^{\circ} 29' 01'' .8$  N., Long.  $100^{\circ} 05' 11'' .7$  E.  
1.1.122 Lat.  $6^{\circ} 29' 02'' .4$  N., Long.  $100^{\circ} 05' 12'' .0$  E.  
1.1.123 Lat.  $6^{\circ} 29' 02'' .9$  N., Long.  $100^{\circ} 05' 12'' .4$  E.  
1.1.124 Lat.  $6^{\circ} 29' 03'' .4$  N., Long.  $100^{\circ} 05' 12'' .8$  E.  
1.1.125 Lat.  $6^{\circ} 29' 03'' .8$  N., Long.  $100^{\circ} 05' 13'' .1$  E.  
1.1.126 Lat.  $6^{\circ} 29' 03'' .9$  N., Long.  $100^{\circ} 05' 13'' .5$  E.  
1.1.127 Lat.  $6^{\circ} 29' 04'' .3$  N., Long.  $100^{\circ} 05' 13'' .7$  E.  
1.1.128 Lat.  $6^{\circ} 29' 04'' .7$  N., Long.  $100^{\circ} 05' 13'' .9$  E.  
1.1.129 Lat.  $6^{\circ} 29' 05'' .1$  N., Long.  $100^{\circ} 05' 14'' .4$  E.  
1.1.130 Lat.  $6^{\circ} 29' 05'' .6$  N., Long.  $100^{\circ} 05' 14'' .8$  E.  
1.1.131 Lat.  $6^{\circ} 29' 06'' .1$  N., Long.  $100^{\circ} 05' 15'' .1$  E.  
1.1.132 Lat.  $6^{\circ} 29' 06'' .5$  N., Long.  $100^{\circ} 05' 15'' .6$  E.  
1.1.133 Lat.  $6^{\circ} 29' 07'' .0$  N., Long.  $100^{\circ} 05' 15'' .9$  E.  
1.1.134 Lat.  $6^{\circ} 29' 07'' .5$  N., Long.  $100^{\circ} 05' 16'' .3$  E.



- 1.1.135 Lat.  $6^{\circ} 29' 07''$  .6 N., Long.  $100^{\circ} 05' 16''$  .5 E.  
1.1.136 Lat.  $6^{\circ} 29' 08''$  .2 N., Long.  $100^{\circ} 05' 16''$  .8 E.  
1.1.137 Lat.  $6^{\circ} 29' 08''$  .5 N., Long.  $100^{\circ} 05' 17''$  .0 E.  
1.1.138 Lat.  $6^{\circ} 29' 09''$  .0 N., Long.  $100^{\circ} 05' 17''$  .3 E.  
1.1.139 Lat.  $6^{\circ} 29' 09''$  .5 N., Long.  $100^{\circ} 05' 17''$  .6 E.  
1.1.140 Lat.  $6^{\circ} 29' 10''$  .1 N., Long.  $100^{\circ} 05' 17''$  .9 E.  
1.1.141 Lat.  $6^{\circ} 29' 10''$  .7 N., Long.  $100^{\circ} 05' 18''$  .2 E.  
1.1.142 Lat.  $6^{\circ} 29' 11''$  .2 N., Long.  $100^{\circ} 05' 18''$  .7 E.  
1.1.143 Lat.  $6^{\circ} 29' 11''$  .7 N., Long.  $100^{\circ} 05' 19''$  .0 E.  
1.1.144 Lat.  $6^{\circ} 29' 12''$  .2 N., Long.  $100^{\circ} 05' 19''$  .4 E.  
1.1.145 Lat.  $6^{\circ} 29' 12''$  .7 N., Long.  $100^{\circ} 05' 19''$  .5 E.  
1.1.146 Lat.  $6^{\circ} 29' 12''$  .9 N., Long.  $100^{\circ} 05' 19''$  .6 E.  
1.1.147 Lat.  $6^{\circ} 29' 13''$  .4 N., Long.  $100^{\circ} 05' 20''$  .0 E.  
1.1.148 Lat.  $6^{\circ} 29' 13''$  .8 N., Long.  $100^{\circ} 05' 20''$  .4 E.  
1.1.149 Lat.  $6^{\circ} 29' 14''$  .0 N., Long.  $100^{\circ} 05' 20''$  .6 E.  
1.1.150 Lat.  $6^{\circ} 29' 14''$  .4 N., Long.  $100^{\circ} 05' 21''$  .1 E.  
1.1.151 Lat.  $6^{\circ} 29' 14''$  .9 N., Long.  $100^{\circ} 05' 21''$  .4 E.  
1.1.152 Lat.  $6^{\circ} 29' 15''$  .4 N., Long.  $100^{\circ} 05' 21''$  .8 E.  
1.1.153 Lat.  $6^{\circ} 29' 15''$  .5 N., Long.  $100^{\circ} 05' 21''$  .9 E.  
1.1.154 Lat.  $6^{\circ} 29' 15''$  .9 N., Long.  $100^{\circ} 05' 22''$  .2 E.  
1.1.155 Lat.  $6^{\circ} 29' 16''$  .4 N., Long.  $100^{\circ} 05' 22''$  .6 E.  
1.1.156 Lat.  $6^{\circ} 29' 16''$  .8 N., Long.  $100^{\circ} 05' 23''$  .0 E.  
1.1.157 Lat.  $6^{\circ} 29' 17''$  .3 N., Long.  $100^{\circ} 05' 23''$  .4 E.  
1.1.158 Lat.  $6^{\circ} 29' 17''$  .7 N., Long.  $100^{\circ} 05' 23''$  .8 E.  
1.1.159 Lat.  $6^{\circ} 29' 18''$  .1 N., Long.  $100^{\circ} 05' 24''$  .2 E.  
1.1.160 Lat.  $6^{\circ} 29' 18''$  .2 N., Long.  $100^{\circ} 05' 24''$  .3 E.  
1.1.161 Lat.  $6^{\circ} 29' 18''$  .7 N., Long.  $100^{\circ} 05' 24''$  .6 E.  
1.1.162 Lat.  $6^{\circ} 29' 19''$  .2 N., Long.  $100^{\circ} 05' 24''$  .9 E.  
1.1.163 Lat.  $6^{\circ} 29' 19''$  .6 N., Long.  $100^{\circ} 05' 25''$  .3 E.  
1.1.164 Lat.  $6^{\circ} 29' 20''$  .1 N., Long.  $100^{\circ} 05' 25''$  .7 E.  
1.1.165 Lat.  $6^{\circ} 29' 21''$  .1 N., Long.  $100^{\circ} 05' 26''$  .5 E.  
1.1.166 Lat.  $6^{\circ} 29' 21''$  .5 N., Long.  $100^{\circ} 05' 26''$  .8 E.  
1.1.167 Lat.  $6^{\circ} 29' 21''$  .8 N., Long.  $100^{\circ} 05' 27''$  .0 E.  
1.1.168 Lat.  $6^{\circ} 29' 22''$  .1 N., Long.  $100^{\circ} 05' 27''$  .4 E.  
1.1.169 Lat.  $6^{\circ} 29' 22''$  .2 N., Long.  $100^{\circ} 05' 27''$  .5 E.  
1.1.170 Lat.  $6^{\circ} 29' 22''$  .4 N., Long.  $100^{\circ} 05' 27''$  .1 E.

- 1.1.171 Lat.  $6^{\circ} 29' 22''$  .7 N., Long.  $100^{\circ} 05' 27''$  .7 E.  
 1.1.172 Lat.  $6^{\circ} 29' 23''$  .3 N., Long.  $100^{\circ} 05' 28''$  .0 E.  
 1.1.173 Lat.  $6^{\circ} 29' 23''$  .8 N., Long.  $100^{\circ} 05' 28''$  .4 E.  
 1.1.174 Lat.  $6^{\circ} 29' 24''$  .3 N., Long.  $100^{\circ} 05' 28''$  .7 E.  
 1.1.175 Lat.  $6^{\circ} 29' 24''$  .7 N., Long.  $100^{\circ} 05' 29''$  .0 E.  
 1.1.176 Lat.  $6^{\circ} 29' 24''$  .6 N., Long.  $100^{\circ} 05' 29''$  .2 E.  
 1.1.177 Lat.  $6^{\circ} 29' 24''$  .8 N., Long.  $100^{\circ} 05' 29''$  .4 E.  
 1.1.178 Lat.  $6^{\circ} 29' 25''$  .1 N., Long.  $100^{\circ} 05' 29''$  .9 E.  
 1.1.179 Lat.  $6^{\circ} 29' 25''$  .5 N., Long.  $100^{\circ} 05' 30''$  .2 E.  
 1.1.180 Lat.  $6^{\circ} 29' 25''$  .9 N., Long.  $100^{\circ} 05' 30''$  .4 E.  
 1.1.181 Lat.  $6^{\circ} 29' 26''$  .2 N., Long.  $100^{\circ} 05' 30''$  .5 E.  
 1.1.182 Lat.  $6^{\circ} 29' 26''$  .2 N., Long.  $100^{\circ} 05' 30''$  .8 E.  
 1.1.183 Lat.  $6^{\circ} 29' 26''$  .7 N., Long.  $100^{\circ} 05' 31''$  .1 E.  
 1.1.184 Lat.  $6^{\circ} 29' 27''$  .3 N., Long.  $100^{\circ} 05' 31''$  .4 E.  
 1.1.185 Lat.  $6^{\circ} 29' 27''$  .8 N., Long.  $100^{\circ} 05' 31''$  .7 E.  
 1.1.186 Lat.  $6^{\circ} 29' 28''$  .4 N., Long.  $100^{\circ} 05' 32''$  .0 E.  
 1.1.187 Lat.  $6^{\circ} 29' 28''$  .7 N., Long.  $100^{\circ} 05' 31''$  .8 E.  
 1.1.188 Lat.  $6^{\circ} 29' 36''$  .0 N., Long.  $100^{\circ} 05' 33''$  .2 E.

## 1.2 Ban Tammalang to Ban Tanyong Kaboi

- 1.2.1 Lat.  $6^{\circ} 31' 52''$  .2 N., Long.  $100^{\circ} 04' 23''$  .2 E.  
 1.2.2 Lat.  $6^{\circ} 31' 46''$  .7 N., Long.  $100^{\circ} 04' 31''$  .2 E.  
 1.2.3 Lat.  $6^{\circ} 31' 46''$  .6 N., Long.  $100^{\circ} 04' 31''$  .3 E.  
 1.2.4 Lat.  $6^{\circ} 31' 46''$  .1 N., Long.  $100^{\circ} 04' 31''$  .9 E.  
 1.2.5 Lat.  $6^{\circ} 31' 46''$  .5 N., Long.  $100^{\circ} 04' 31''$  .3 E.  
 1.2.6 Lat.  $6^{\circ} 31' 46''$  .1 N., Long.  $100^{\circ} 04' 31''$  .8 E.  
 1.2.7 Lat.  $6^{\circ} 31' 46''$  .1 N., Long.  $100^{\circ} 04' 31''$  .9 E.  
 1.2.8 Lat.  $6^{\circ} 31' 45''$  .6 N., Long.  $100^{\circ} 04' 32''$  .2 E.  
 1.2.9 Lat.  $6^{\circ} 31' 45''$  .5 N., Long.  $100^{\circ} 04' 32''$  .4 E.  
 1.2.10 Lat.  $6^{\circ} 31' 45''$  .0 N., Long.  $100^{\circ} 04' 32''$  .4 E.  
 1.2.11 Lat.  $6^{\circ} 31' 44''$  .6 N., Long.  $100^{\circ} 04' 32''$  .8 E.  
 1.2.12 Lat.  $6^{\circ} 31' 44''$  .1 N., Long.  $100^{\circ} 04' 33''$  .1 E.  
 1.2.13 Lat.  $6^{\circ} 31' 43''$  .7 N., Long.  $100^{\circ} 04' 33''$  .5 E.  
 1.2.14 Lat.  $6^{\circ} 31' 43''$  .2 N., Long.  $100^{\circ} 04' 33''$  .8 E.  
 1.2.15 Lat.  $6^{\circ} 31' 43''$  .1 N., Long.  $100^{\circ} 04' 33''$  .9 E.  
 1.2.16 Lat.  $6^{\circ} 31' 43''$  .0 N., Long.  $100^{\circ} 04' 33''$  .8 E.  
 1.2.17 Lat.  $6^{\circ} 31' 42''$  .6 N., Long.  $100^{\circ} 04' 34''$  .2 E.

- 1.2.18 Lat.  $6^{\circ} 31' 42'' .3$  N., Long.  $100^{\circ} 04' 34'' .4$  E.  
1.2.19 Lat.  $6^{\circ} 31' 42'' .2$  N., Long.  $100^{\circ} 04' 34'' .5$  E.  
1.2.20 Lat.  $6^{\circ} 31' 42'' .2$  N., Long.  $100^{\circ} 04' 34'' .7$  E.  
1.2.21 Lat.  $6^{\circ} 31' 41'' .9$  N., Long.  $100^{\circ} 04' 34'' .8$  E.  
1.2.22 Lat.  $6^{\circ} 31' 41'' .5$  N., Long.  $100^{\circ} 04' 35'' .2$  E.  
1.2.23 Lat.  $6^{\circ} 31' 41'' .1$  N., Long.  $100^{\circ} 04' 35'' .7$  E.  
1.2.24 Lat.  $6^{\circ} 31' 40'' .8$  N., Long.  $100^{\circ} 04' 36'' .2$  E.  
1.2.25 Lat.  $6^{\circ} 31' 40'' .6$  N., Long.  $100^{\circ} 04' 36'' .7$  E.  
1.2.26 Lat.  $6^{\circ} 31' 40'' .5$  N., Long.  $100^{\circ} 04' 37'' .0$  E.  
1.2.27 Lat.  $6^{\circ} 31' 40'' .5$  N., Long.  $100^{\circ} 04' 37'' .2$  E.  
1.2.28 Lat.  $6^{\circ} 31' 40'' .3$  N., Long.  $100^{\circ} 04' 37'' .8$  E.  
1.2.29 Lat.  $6^{\circ} 31' 40'' .0$  N., Long.  $100^{\circ} 04' 38'' .3$  E.  
1.2.30 Lat.  $6^{\circ} 31' 39'' .8$  N., Long.  $100^{\circ} 04' 38'' .8$  E.  
1.2.31 Lat.  $6^{\circ} 31' 39'' .6$  N., Long.  $100^{\circ} 04' 39'' .2$  E.  
1.2.32 Lat.  $6^{\circ} 31' 39'' .3$  N., Long.  $100^{\circ} 04' 39'' .6$  E.  
1.2.33 Lat.  $6^{\circ} 31' 38'' .9$  N., Long.  $100^{\circ} 04' 40'' .1$  E.  
1.2.34 Lat.  $6^{\circ} 31' 38'' .5$  N., Long.  $100^{\circ} 04' 40'' .6$  E.  
1.2.35 Lat.  $6^{\circ} 31' 38'' .2$  N., Long.  $100^{\circ} 04' 41'' .1$  E.  
1.2.36 Lat.  $6^{\circ} 31' 37'' .7$  N., Long.  $100^{\circ} 04' 41'' .6$  E.  
1.2.37 Lat.  $6^{\circ} 31' 37'' .5$  N., Long.  $100^{\circ} 04' 41'' .8$  E.  
1.2.38 Lat.  $6^{\circ} 31' 37'' .4$  N., Long.  $100^{\circ} 04' 42'' .2$  E.  
1.2.39 Lat.  $6^{\circ} 31' 36'' .9$  N., Long.  $100^{\circ} 04' 42'' .7$  E.  
1.2.40 Lat.  $6^{\circ} 31' 36'' .8$  N., Long.  $100^{\circ} 04' 42'' .9$  E.  
1.2.41 Lat.  $6^{\circ} 31' 36'' .3$  N., Long.  $100^{\circ} 04' 43'' .3$  E.  
1.2.42 Lat.  $6^{\circ} 31' 35'' .9$  N., Long.  $100^{\circ} 04' 43'' .6$  E.  
1.2.43 Lat.  $6^{\circ} 31' 35'' .4$  N., Long.  $100^{\circ} 04' 44'' .1$  E.  
1.2.44 Lat.  $6^{\circ} 31' 35'' .0$  N., Long.  $100^{\circ} 04' 44'' .6$  E.  
1.2.45 Lat.  $6^{\circ} 31' 34'' .6$  N., Long.  $100^{\circ} 04' 45'' .0$  E.  
1.2.46 Lat.  $6^{\circ} 31' 34'' .1$  N., Long.  $100^{\circ} 04' 45'' .5$  E.  
1.2.47 Lat.  $6^{\circ} 31' 33'' .7$  N., Long.  $100^{\circ} 04' 46'' .0$  E.  
1.2.48 Lat.  $6^{\circ} 31' 33'' .3$  N., Long.  $100^{\circ} 04' 46'' .4$  E.  
1.2.49 Lat.  $6^{\circ} 31' 32'' .8$  N., Long.  $100^{\circ} 04' 46'' .9$  E.  
1.2.50 Lat.  $6^{\circ} 31' 32'' .4$  N., Long.  $100^{\circ} 04' 47'' .3$  E.  
1.2.51 Lat.  $6^{\circ} 31' 32'' .0$  N., Long.  $100^{\circ} 04' 47'' .8$  E.  
1.2.52 Lat.  $6^{\circ} 31' 31'' .5$  N., Long.  $100^{\circ} 04' 48'' .3$  E.  
1.2.53 Lat.  $6^{\circ} 31' 31'' .1$  N., Long.  $100^{\circ} 04' 48'' .8$  E.

- 1.2.54 Lat.  $6^{\circ} 31' 30''$  .9 N., Long.  $100^{\circ} 04' 48''$  .8 E.  
1.2.55 Lat.  $6^{\circ} 31' 30''$  .6 N., Long.  $100^{\circ} 04' 49''$  .4 E.  
1.2.56 Lat.  $6^{\circ} 31' 30''$  .2 N., Long.  $100^{\circ} 04' 49''$  .9 E.  
1.2.57 Lat.  $6^{\circ} 31' 29''$  .8 N., Long.  $100^{\circ} 04' 50''$  .3 E.  
1.2.58 Lat.  $6^{\circ} 31' 29''$  .4 N., Long.  $100^{\circ} 04' 50''$  .7 E.  
1.2.59 Lat.  $6^{\circ} 31' 28''$  .9 N., Long.  $100^{\circ} 04' 51''$  .1 E.  
1.2.60 Lat.  $6^{\circ} 31' 28''$  .6 N., Long.  $100^{\circ} 04' 51''$  .6 E.  
1.2.61 Lat.  $6^{\circ} 31' 28''$  .2 N., Long.  $100^{\circ} 04' 52''$  .1 E.  
1.2.62 Lat.  $6^{\circ} 31' 27''$  .7 N., Long.  $100^{\circ} 04' 52''$  .5 E.  
1.2.63 Lat.  $6^{\circ} 31' 27''$  .3 N., Long.  $100^{\circ} 04' 53''$  .0 E.  
1.2.64 Lat.  $6^{\circ} 31' 26''$  .9 N., Long.  $100^{\circ} 04' 53''$  .4 E.  
1.2.65 Lat.  $6^{\circ} 31' 26''$  .5 N., Long.  $100^{\circ} 04' 53''$  .9 E.  
1.2.66 Lat.  $6^{\circ} 31' 26''$  .0 N., Long.  $100^{\circ} 04' 54''$  .3 E.  
1.2.67 Lat.  $6^{\circ} 31' 25''$  .8 N., Long.  $100^{\circ} 04' 54''$  .7 E.  
1.2.68 Lat.  $6^{\circ} 31' 25''$  .2 N., Long.  $100^{\circ} 04' 55''$  .1 E.  
1.2.69 Lat.  $6^{\circ} 31' 25''$  .0 N., Long.  $100^{\circ} 04' 55''$  .5 E.  
1.2.70 Lat.  $6^{\circ} 31' 24''$  .9 N., Long.  $100^{\circ} 04' 55''$  .3 E.  
1.2.71 Lat.  $6^{\circ} 31' 24''$  .6 N., Long.  $100^{\circ} 04' 55''$  .8 E.  
1.2.72 Lat.  $6^{\circ} 31' 24''$  .1 N., Long.  $100^{\circ} 04' 56''$  .3 E.  
1.2.73 Lat.  $6^{\circ} 31' 23''$  .6 N., Long.  $100^{\circ} 04' 56''$  .7 E.  
1.2.74 Lat.  $6^{\circ} 31' 23''$  .2 N., Long.  $100^{\circ} 04' 57''$  .2 E.  
1.2.75 Lat.  $6^{\circ} 31' 22''$  .7 N., Long.  $100^{\circ} 04' 57''$  .6 E.  
1.2.76 Lat.  $6^{\circ} 31' 22''$  .3 N., Long.  $100^{\circ} 04' 58''$  .1 E.  
1.2.77 Lat.  $6^{\circ} 31' 21''$  .9 N., Long.  $100^{\circ} 04' 58''$  .5 E.  
1.2.78 Lat.  $6^{\circ} 31' 21''$  .4 N., Long.  $100^{\circ} 04' 58''$  .9 E.  
1.2.79 Lat.  $6^{\circ} 31' 21''$  .0 N., Long.  $100^{\circ} 04' 59''$  .4 E.  
1.2.80 Lat.  $6^{\circ} 31' 20''$  .6 N., Long.  $100^{\circ} 04' 59''$  .8 E.  
1.2.81 Lat.  $6^{\circ} 31' 20''$  .1 N., Long.  $100^{\circ} 05' 00''$  .3 E.  
1.2.82 Lat.  $6^{\circ} 31' 19''$  .7 N., Long.  $100^{\circ} 05' 00''$  .7 E.  
1.2.83 Lat.  $6^{\circ} 31' 19''$  .6 N., Long.  $100^{\circ} 05' 01''$  .0 E.  
1.2.84 Lat.  $6^{\circ} 31' 19''$  .2 N., Long.  $100^{\circ} 05' 01''$  .4 E.  
1.2.85 Lat.  $6^{\circ} 31' 18''$  .8 N., Long.  $100^{\circ} 05' 01''$  .9 E.  
1.2.86 Lat.  $6^{\circ} 31' 18''$  .6 N., Long.  $100^{\circ} 05' 02''$  .1 E.  
1.2.87 Lat.  $6^{\circ} 31' 18''$  .5 N., Long.  $100^{\circ} 05' 02''$  .1 E.

- 1.2.88 Lat.  $6^{\circ} 31' 18''$ .4 N., Long.  $100^{\circ} 05' 02''$ .3 E.  
1.2.89 Lat.  $6^{\circ} 31' 18''$ .0 N., Long.  $100^{\circ} 05' 02''$ .8 E.  
1.2.90 Lat.  $6^{\circ} 31' 17''$ .7 N., Long.  $100^{\circ} 05' 03''$ .3 E.  
1.2.91 Lat.  $6^{\circ} 31' 17''$ .3 N., Long.  $100^{\circ} 05' 03''$ .8 E.  
1.2.92 Lat.  $6^{\circ} 31' 17''$ .0 N., Long.  $100^{\circ} 05' 04''$ .3 E.  
1.2.93 Lat.  $6^{\circ} 31' 16''$ .5 N., Long.  $100^{\circ} 05' 04''$ .7 E.  
1.2.94 Lat.  $6^{\circ} 31' 16''$ .2 N., Long.  $100^{\circ} 05' 05''$ .3 E.  
1.2.95 Lat.  $6^{\circ} 31' 15''$ .8 N., Long.  $100^{\circ} 05' 05''$ .7 E.  
1.2.96 Lat.  $6^{\circ} 31' 15''$ .3 N., Long.  $100^{\circ} 05' 06''$ .2 E.  
1.2.97 Lat.  $6^{\circ} 31' 14''$ .9 N., Long.  $100^{\circ} 05' 06''$ .7 E.  
1.2.98 Lat.  $6^{\circ} 31' 14''$ .5 N., Long.  $100^{\circ} 05' 07''$ .2 E.  
1.2.99 Lat.  $6^{\circ} 31' 14''$ .0 N., Long.  $100^{\circ} 05' 07''$ .7 E.  
1.2.100 Lat.  $6^{\circ} 31' 13''$ .6 N., Long.  $100^{\circ} 05' 08''$ .1 E.  
1.2.101 Lat.  $6^{\circ} 31' 13''$ .1 N., Long.  $100^{\circ} 05' 08''$ .6 E.  
1.2.102 Lat.  $6^{\circ} 31' 12''$ .7 N., Long.  $100^{\circ} 05' 08''$ .9 E.  
1.2.103 Lat.  $6^{\circ} 31' 12''$ .8 N., Long.  $100^{\circ} 05' 09''$ .0 E.  
1.2.104 Lat.  $6^{\circ} 31' 12''$ .8 N., Long.  $100^{\circ} 05' 09''$ .1 E.  
1.2.105 Lat.  $6^{\circ} 31' 12''$ .6 N., Long.  $100^{\circ} 05' 09''$ .4 E.  
1.2.106 Lat.  $6^{\circ} 31' 12''$ .2 N., Long.  $100^{\circ} 05' 09''$ .9 E.  
1.2.107 Lat.  $6^{\circ} 31' 11''$ .9 N., Long.  $100^{\circ} 05' 10''$ .4 E.  
1.2.108 Lat.  $6^{\circ} 31' 11''$ .4 N., Long.  $100^{\circ} 05' 10''$ .9 E.  
1.2.109 Lat.  $6^{\circ} 31' 11''$ .0 N., Long.  $100^{\circ} 05' 11''$ .2 E.  
1.2.110 Lat.  $6^{\circ} 31' 10''$ .6 N., Long.  $100^{\circ} 05' 11''$ .7 E.  
1.2.111 Lat.  $6^{\circ} 31' 10''$ .1 N., Long.  $100^{\circ} 05' 12''$ .2 E.  
1.2.112 Lat.  $6^{\circ} 31' 09''$ .7 N., Long.  $100^{\circ} 05' 12''$ .7 E.  
1.2.113 Lat.  $6^{\circ} 31' 09''$ .2 N., Long.  $100^{\circ} 05' 13''$ .1 E.  
1.2.114 Lat.  $6^{\circ} 31' 08''$ .7 N., Long.  $100^{\circ} 05' 13''$ .6 E.  
1.2.115 Lat.  $6^{\circ} 31' 08''$ .3 N., Long.  $100^{\circ} 05' 14''$ .0 E.  
1.2.116 Lat.  $6^{\circ} 31' 07''$ .8 N., Long.  $100^{\circ} 05' 14''$ .5 E.  
1.2.117 Lat.  $6^{\circ} 31' 07''$ .3 N., Long.  $100^{\circ} 05' 14''$ .9 E.  
1.2.118 Lat.  $6^{\circ} 31' 06''$ .9 N., Long.  $100^{\circ} 05' 15''$ .4 E.  
1.2.119 Lat.  $6^{\circ} 31' 06''$ .4 N., Long.  $100^{\circ} 05' 15''$ .8 E.  
1.2.120 Lat.  $6^{\circ} 31' 06''$ .1 N., Long.  $100^{\circ} 05' 16''$ .3 E.  
1.2.121 Lat.  $6^{\circ} 31' 06''$ .2 N., Long.  $100^{\circ} 05' 16''$ .3 E.

- 1.2.122 Lat.  $6^{\circ} 31' 06''$  .0 N., Long.  $100^{\circ} 05' 16''$  .2 E.  
1.2.123 Lat.  $6^{\circ} 31' 06''$  .0 N., Long.  $100^{\circ} 05' 16''$  .3 E.  
1.2.124 Lat.  $6^{\circ} 31' 05''$  .5 N., Long.  $100^{\circ} 05' 16''$  .7 E.  
1.2.125 Lat.  $6^{\circ} 31' 05''$  .0 N., Long.  $100^{\circ} 05' 17''$  .2 E.  
1.2.126 Lat.  $6^{\circ} 31' 04''$  .5 N., Long.  $100^{\circ} 05' 17''$  .6 E.  
1.2.127 Lat.  $6^{\circ} 31' 04''$  .0 N., Long.  $100^{\circ} 05' 18''$  .1 E.  
1.2.128 Lat.  $6^{\circ} 31' 03''$  .6 N., Long.  $100^{\circ} 05' 18''$  .5 E.  
1.2.129 Lat.  $6^{\circ} 31' 03''$  .1 N., Long.  $100^{\circ} 05' 19''$  .0 E.  
1.2.130 Lat.  $6^{\circ} 31' 02''$  .7 N., Long.  $100^{\circ} 05' 19''$  .4 E.  
1.2.131 Lat.  $6^{\circ} 31' 02''$  .3 N., Long.  $100^{\circ} 05' 19''$  .9 E.  
1.2.132 Lat.  $6^{\circ} 31' 01''$  .8 N., Long.  $100^{\circ} 05' 20''$  .3 E.  
1.2.133 Lat.  $6^{\circ} 31' 01''$  .3 N., Long.  $100^{\circ} 05' 20''$  .7 E.  
1.2.134 Lat.  $6^{\circ} 31' 00''$  .8 N., Long.  $100^{\circ} 05' 21''$  .2 E.  
1.2.135 Lat.  $6^{\circ} 31' 00''$  .6 N., Long.  $100^{\circ} 05' 21''$  .2 E.  
1.2.136 Lat.  $6^{\circ} 31' 00''$  .5 N., Long.  $100^{\circ} 05' 21''$  .7 E.  
1.2.137 Lat.  $6^{\circ} 31' 00''$  .2 N., Long.  $100^{\circ} 05' 22''$  .2 E.  
1.2.138 Lat.  $6^{\circ} 30' 59''$  .8 N., Long.  $100^{\circ} 05' 22''$  .7 E.  
1.2.139 Lat.  $6^{\circ} 30' 59''$  .6 N., Long.  $100^{\circ} 05' 22''$  .8 E.  
1.2.140 Lat.  $6^{\circ} 30' 59''$  .4 N., Long.  $100^{\circ} 05' 23''$  .1 E.  
1.2.141 Lat.  $6^{\circ} 30' 59''$  .1 N., Long.  $100^{\circ} 05' 23''$  .6 E.  
1.2.142 Lat.  $6^{\circ} 30' 58''$  .7 N., Long.  $100^{\circ} 05' 24''$  .2 E.  
1.2.143 Lat.  $6^{\circ} 30' 58''$  .3 N., Long.  $100^{\circ} 05' 24''$  .6 E.  
1.2.144 Lat.  $6^{\circ} 30' 57''$  .9 N., Long.  $100^{\circ} 05' 25''$  .1 E.  
1.2.145 Lat.  $6^{\circ} 30' 57''$  .4 N., Long.  $100^{\circ} 05' 25''$  .6 E.  
1.2.146 Lat.  $6^{\circ} 30' 57''$  .0 N., Long.  $100^{\circ} 05' 26''$  .1 E.  
1.2.147 Lat.  $6^{\circ} 30' 56''$  .2 N., Long.  $100^{\circ} 05' 27''$  .1 E.  
1.2.148 Lat.  $6^{\circ} 30' 55''$  .7 N., Long.  $100^{\circ} 05' 27''$  .5 E.  
1.2.149 Lat.  $6^{\circ} 30' 55''$  .3 N., Long.  $100^{\circ} 05' 28''$  .0 E.  
1.2.150 Lat.  $6^{\circ} 30' 54''$  .8 N., Long.  $100^{\circ} 05' 28''$  .5 E.  
1.2.151 Lat.  $6^{\circ} 30' 54''$  .9 N., Long.  $100^{\circ} 05' 28''$  .6 E.  
1.2.152 Lat.  $6^{\circ} 30' 54''$  .4 N., Long.  $100^{\circ} 05' 29''$  .0 E.  
1.2.153 Lat.  $6^{\circ} 30' 53''$  .9 N., Long.  $100^{\circ} 05' 29''$  .5 E.  
1.2.154 Lat.  $6^{\circ} 30' 53''$  .6 N., Long.  $100^{\circ} 05' 29''$  .9 E.  
1.2.155 Lat.  $6^{\circ} 30' 53''$  .4 N., Long.  $100^{\circ} 05' 30''$  .0 E.

- 1.2.156 Lat.  $6^{\circ} 30' 53'' .4$  N., Long.  $100^{\circ} 05' 29'' .9$  E.  
1.2.157 Lat.  $6^{\circ} 30' 53'' .3$  N., Long.  $100^{\circ} 05' 30'' .4$  E.  
1.2.158 Lat.  $6^{\circ} 30' 52'' .9$  N., Long.  $100^{\circ} 05' 30'' .8$  E.  
1.2.159 Lat.  $6^{\circ} 30' 52'' .5$  N., Long.  $100^{\circ} 05' 31'' .3$  E.  
1.2.160 Lat.  $6^{\circ} 30' 52'' .1$  N., Long.  $100^{\circ} 05' 31'' .8$  E.  
1.2.161 Lat.  $6^{\circ} 30' 51'' .6$  N., Long.  $100^{\circ} 05' 32'' .1$  E.  
1.2.162 Lat.  $6^{\circ} 30' 51'' .1$  N., Long.  $100^{\circ} 05' 32'' .5$  E.  
1.2.163 Lat.  $6^{\circ} 30' 50'' .7$  N., Long.  $100^{\circ} 05' 32'' .9$  E.  
1.2.164 Lat.  $6^{\circ} 30' 50'' .3$  N., Long.  $100^{\circ} 05' 33'' .4$  E.  
1.2.165 Lat.  $6^{\circ} 30' 49'' .9$  N., Long.  $100^{\circ} 05' 33'' .9$  E.  
1.2.166 Lat.  $6^{\circ} 30' 49'' .4$  N., Long.  $100^{\circ} 05' 34'' .3$  E.  
1.2.167 Lat.  $6^{\circ} 30' 48'' .9$  N., Long.  $100^{\circ} 05' 34'' .8$  E.  
1.2.168 Lat.  $6^{\circ} 30' 48'' .5$  N., Long.  $100^{\circ} 05' 35'' .2$  E.  
1.2.169 Lat.  $6^{\circ} 30' 48'' .0$  N., Long.  $100^{\circ} 05' 35'' .7$  E.  
1.2.170 Lat.  $6^{\circ} 30' 47'' .6$  N., Long.  $100^{\circ} 05' 36'' .1$  E.  
1.2.171 Lat.  $6^{\circ} 30' 47'' .4$  N., Long.  $100^{\circ} 05' 36'' .4$  E.  
1.2.172 Lat.  $6^{\circ} 30' 47'' .1$  N., Long.  $100^{\circ} 05' 36'' .4$  E.  
1.2.173 Lat.  $6^{\circ} 30' 46'' .6$  N., Long.  $100^{\circ} 05' 36'' .8$  E.  
1.2.174 Lat.  $6^{\circ} 30' 46'' .3$  N., Long.  $100^{\circ} 05' 37'' .2$  E.  
1.2.175 Lat.  $6^{\circ} 30' 46'' .1$  N., Long.  $100^{\circ} 05' 37'' .7$  E.  
1.2.176 Lat.  $6^{\circ} 30' 46'' .0$  N., Long.  $100^{\circ} 05' 37'' .7$  E.  
1.2.177 Lat.  $6^{\circ} 30' 45'' .5$  N., Long.  $100^{\circ} 05' 38'' .1$  E.  
1.2.178 Lat.  $6^{\circ} 30' 45'' .2$  N., Long.  $100^{\circ} 05' 38'' .6$  E.  
1.2.179 Lat.  $6^{\circ} 30' 44'' .8$  N., Long.  $100^{\circ} 05' 39'' .1$  E.  
1.2.180 Lat.  $6^{\circ} 30' 44'' .5$  N., Long.  $100^{\circ} 05' 39'' .6$  E.  
1.2.181 Lat.  $6^{\circ} 30' 44'' .1$  N., Long.  $100^{\circ} 05' 40'' .0$  E.  
1.2.182 Lat.  $6^{\circ} 30' 43'' .7$  N., Long.  $100^{\circ} 05' 40'' .5$  E.  
1.2.183 Lat.  $6^{\circ} 30' 43'' .3$  N., Long.  $100^{\circ} 05' 41'' .0$  E.  
1.2.184 Lat.  $6^{\circ} 30' 42'' .9$  N., Long.  $100^{\circ} 05' 41'' .5$  E.  
1.2.185 Lat.  $6^{\circ} 30' 43'' .3$  N., Long.  $100^{\circ} 05' 41'' .0$  E.  
1.2.186 Lat.  $6^{\circ} 30' 42'' .5$  N., Long.  $100^{\circ} 05' 41'' .9$  E.  
1.2.187 Lat.  $6^{\circ} 30' 42'' .1$  N., Long.  $100^{\circ} 05' 42'' .4$  E.  
1.2.188 Lat.  $6^{\circ} 30' 41'' .7$  N., Long.  $100^{\circ} 05' 42'' .9$  E.  
1.2.189 Lat.  $6^{\circ} 30' 41'' .4$  N., Long.  $100^{\circ} 05' 43'' .4$  E.  
1.2.190 Lat.  $6^{\circ} 30' 41'' .3$  N., Long.  $100^{\circ} 05' 43'' .9$  E.  
1.2.191 Lat.  $6^{\circ} 30' 36'' .8$  N., Long.  $100^{\circ} 05' 47'' .8$  E.

2. Vessels should avoid anchoring or trawling in the vicinity of the submarine power cable routes.

3. These submarine power cables will be included in the next New Edition of charts 362 and 045, Charts 350 and 309 have been updated by Notice to Mariners.

4. Former Notice No. 7/2552 (P) is cancelled.

**Charts affected :** Thai Chart Nos. 350, 309, 362 and 045.

**Reported from :** Provincial Electricity Authority, dated 22<sup>nd</sup> July 2009.

**Issued by the Hydrographic Department,  
Royal Thai Navy, Bangkok,  
17<sup>th</sup> December 2009.**